

ETHIOPIA


WASH in small and medium towns

AID 9428



Householder interview in Huruta town

AID 9428 –HURUTA Town
Evaluation mission's photos
- Dec. 2015 -



Ph. 1: Huruta town: overview from the spring's site



Ph. 2: Hutura gateway



Ph. 3: Arrival in Huruta



Ph. 4: Huruta main road



Ph. 5: Huruta simple games



Ph. 6: Huruta Bus Station



Ph. 7: Huruta market



Ph. 8: Huruta Town Water Utility



Ph. 9: Huruta TWU office



Ph. 10: Huruta TWU office



Ph. 11: Huruta TWU Billing payment desk



Ph. 12: Account officer



Ph. 13: TWU toilets



Ph. 14: Delivery of project equipments and tools




Ph. 15: TWU Toyota Pick Up (Supplied by the project)



Ph. 16: The gorge of the spring's sites




Ph. 17: Fincha 1 spring, overflow



Ph. 18: Fincha 2 spring



Ph. 19: Amado spring: Overflow.



Ph. 20: Sediment and gravel inside the intake manhole



Ph. 21: Transmission pipe, not buried



Ph. 22: River Varecha crossing (chan. 4+875 – 1995 masl)



Ph. 23: New Huruta Tank , Vol= 500 m3; el. 2075 masl



Ph. 24: Tank outlet DN 300 mm, to the town network



Ph. 25: Transmission pipe washout



Ph. 26: WS Network Node J.4 at the entrance of the town



Ph. 27: Water point n. 1 (out of service)



Ph. 28: Water point n. 2 in Drejarti (Slum area)



Ph. 29: Water point n. 3 (out of service)



Ph. 30: Water point n. 5 (out of service)



Ph. 31: Queue at Water point n. 4



Ph. 32: Toilet at the bus station/market



Ph. 33: Toilet septic tank



Ph. 34: Toilet Water connection



Ph. 35: Toilet seats



Ph. 36: Toilet showers



Ph. 37: Sludge dry beds



Ph. 38: Billing Reader



Ph. 39: Household Water connection



Ph. 40: The dissidents



Ph. 41: Householder Interview n. 1



Ph. 42: Householder interview n. 2



Ph. 43: Householder interview n. 4



Ph. 44: Householder interview n. 5



Ph. 45: At the primary school: Interview n. 5



Ph. 46: Householder interview



Ph. 47: Wine Hotel's owner interview



Ph. 48: TWU's Manager interview

AID 9428 –DURAME Town
Evaluation mission's photos
Dec. 2015



Ph. 1- Project sign



Ph. 2: TWU building



Ph. 3: TWU building



Ph. 4: TWU building



Ph. 5: TWU-WC



Ph. 6: billing



Ph. 7: Borehole BH1 site



Ph. 8: Borehole BH1



Ph. 9: BH1 (interior)



Ph. 10: Borehole BH3



Ph. 11: Borehole BH3 valves



Ph. 12: Makane Booster, step aerator and water reservoir



Ph. 13: Booster1: n. 2 pump sets



Ph. 14: KMG water tank



Ph. 15: Break pressure tank (BPT)



Ph. 16: Borehole BH4 (Benara)




Ph. 17: Borehole BH4 valves



Ph. 18: Borehole BH2 at Benara site



Ph. 19: Benara Booster2, step areator and wet tank



Ph. 20: aerator – red iron deposits



Ph. 21: Booster pumping sets



Ph. 22: BPT



Ph. 23: Latrine 1- market



Ph. 24: Latrine1 market



Ph. 25: Septic tank 1



Ph. 26: Latrine2



Ph. 27: Septic tank 2



Ph. 28: Pipe break



Ph. 29: WP2 (Ambo)



Ph. 30: WP2



Ph. 31: WP3



Ph. 32: WP4



Ph. 33: TWU's manager-interview



Ph. 34: Durame hospital



Ph. 35: Hospital's Manager interview



Ph. 36: Household connection -tap



Ph. 37: Durame - interview



Ph. 38: Durame - interview



Ph. 39: Durame - interview



Ph. 40: Durame - interview



Ph. 41: interview at coffee factory

AID 9428 –SHIRE E. Town
Evaluation mission's photos
Dec. 2015



Ph. 1-Shire town



Ph. 2: TWU office




Ph. 3: Billing



Ph. 4: TWU - archives



Ph. 5:pick-up



Ph. 6: Well field site



Ph. 7: BHA



Ph. 8: Booster buildings



Ph. 9: Booster pump sets



Ph. 10: P. generator



Ph. 11: Electr. overhead line collapsed



Ph. 12: new water Tank



Ph. 13: Chlorization plant (out of order)



Ph. 14: Latrine at the bus station



Ph. 15: Latrine 1 at the bus station



Ph. 16: Latrine 1 ticketing



Ph. 17: Latrine 1 (int.)




Ph. 18: Showers Latrine 1



Ph. 19: Latrine 2 at the market 1



Ph. 20: Latrine 3 at Market 2



Ph. 21: TWU's manager interview



Ph. 22: Interview 1



Ph. 23: Interview 2



Ph. 24: Interview 3



Ph. 25: Interview 4



Ph. 26: Interview 5



Ph. 27: Interview 6



Ph. 28: Interview 7 (Africa Hotel manager)

AID 9428 –LIMU GENNET Town
Evaluation mission's photos
Dec. 2015



Ph. 1-Limu_Gennet




Ph. 2: Limu TWU office



Ph. 3: TWU - Toilette



Ph. 4: TWU - WC



Ph. 5:Borehole BH1b



Ph. 6: Borehole BH1 burned by lightning



Ph. 7: Borehole BH2 and Pumping station



Ph. 8: Borehole BH2 flow test



Ph. 9: Pumping station generator



Ph. 10: Tank



Ph. 11: Dry sludge bed



Ph. 12: Limu Market



Ph. 13: Market WC ext.



Ph. 14: Toilette Market ext



Ph. 15: Market Toilette int.



Ph. 16: Bus station



Ph. 17: Latrine at the Bus station



Ph. 18: Water Point (WP) 1



Ph. 19: WP2



Ph. 20: WP3



Ph. 21: Pick-up



Ph. 22: TWU's manager interview



Ph. 23: Limu Hospital



Ph. 24: Hospital's manager - Interview 13



Ph. 25: Primary School 1



Ph. 26: Shool manager Interview 11



Ph. 27: School



Ph. 28: High-school



Ph. 29: High school's manager – Interview 12.



Ph. 30: Interview 1



Ph. 31: Interview 2



Ph. 32: Interview 3



Ph. 33: Interview 4



Ph. 34: Interview 5



Ph. 35: Interview 6



Ph. 36: Interview 7



Ph. 37: Interview 8



Ph. 38: Interview 9



Ph. 39: Interview 10